



Completion Report

conducted for

HOUSING ASSOCIATION

Document No.

UIS-226/20

Job Number

TBC

Location

1-24 Belmont Court

Hertfordshire

Prepared by

Toby Judge

Gang Attending

RM01

Operative 2

RM01

Operative 1

RM01

Job Details

Question	Response	Details
Job Initiation		
Pre-Start photo		
		
Appendix 1	Appendix 2	Appendix 3 Appendix 4 Appendix 5 Appendix 6
		
Appendix 7	Appendix 8	Appendix 9 Appendix 10
Job Started		
Health & Safety		
Risk Assessment completed	Yes	
Underground Services Identified	Yes	
Pedestrian Access control	Yes	
Site secured	Yes	
Photo of site		
Works completion		
Works completed	Yes	
Works reinstated	Yes	
Site cleared	Yes	

Description of works undertaken	<p>We attended site regarding the leak affecting the property.</p> <p>We CAT Scanned the proposed working area and set up a safe site.</p> <p>We excavated the external stop tap and exposed the pipe work. The leak was a 22mm stop tap (Appendix 4) the pipe work had a pin hole.</p> <p>We cut out the failed stop tap and copper pipe work, we installed a new 25mm MDPE inline stop valve</p> <p>We made new connections and tested our installation.</p> <p>We backfilled with as dug material and reinstated the concrete footpath</p> <p>We cleared site.</p>
Please take pictures of each working stage and any relevant additional information (i.e pre start damage etc.).	
Site drawing	
Site Left	
Fittings Used	
Hours Spent	

Materials and Equipment

Question	Response	Details
----------	----------	---------

Media




Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10